



REPORT

2023 Annual Compliance Reporting

Environmental Compliance Approval Reference Number 5005-CSYL97

Submitted to:

Heidelberg Materials Canada Limited

1370 Highway 49
Picton, Ontario
K0K 2T0


Submitted by:

WSP Canada Inc.

1931 Robertson Road
Ottawa, Ontario, K2H 5B7, Canada
+1 613 592 9600

CA0019006.6372

August 30, 2024



Distribution List

Electronic Copy - Heidelberg Materials Canada Limited

Electronic Copy - WSP Canada Inc.

Table of Contents

1.0 INTRODUCTION	1
2.0 ECA CONDITION 16.1(A): COMPLIANCE STATEMENT	1
3.0 ECA CONDITION 16.1(B): EMISSIONS SUMMARY TABLE AND ACOUSTIC ASSESSMENT SUMMARY TABLE	1
4.0 ECA CONDITION 16.1(C): CLINKER AND CEMENT PRODUCTION	2
5.0 ECA CONDITION 16.1(D): ALCF FEED RATE AND WEIGHT PERCENTAGE	2
6.0 ECA CONDITION 16.1(E): ALCF THERMAL REPLACEMENT OF CONVENTIONAL FUELS	2
7.0 ECA CONDITION 16.1(F): ALCF CEM, CPM, SOURCE TESTING AND CARBON DIOXIDE EMMISSIONS INTENSITY TESTING	2
8.0 ECA CONDITION 16.1(G): SUMMARY OF OPERATIONAL EVENTS THAT MAY HAVE NEGATIVELY IMPACTED THE ENVIRONMENT	2
9.0 ECA CONDITION 16.1(H): SUMMARY OF COMPLAINTS	2
10.0 LIMITATIONS	3
11.0 CLOSURE	3

TABLES

Table 1: 2023 Clinker and Cement Production	2
---	---

ATTACHMENTS

Attachment 1

Compliance and Performance Limit Signed Statement

Attachment 2

Emissions Summary Tables

Attachment 3

Acoustic Assessment Summary Table

Attachment 4

Summary of Operational Events that May Have Negatively Impacted the Environment

ATTACHMENT 1

**Compliance and Performance Limit
Signed Statement**



ATTACHMENT 2



--	--	--	--	--

--	--	--	--	--	--

August 30Be0.2224

Start Date	Event	SAC Reference #	Reason For Incident	Corrective Action
April 1, 2023	Elevated Opacity	1-346QES	A PLC power supply failed. Lost communication on PLC network	Replaced power supply which allowed PLC to



wsp.com